```
UNCLASSIFIED
MSG DTG 281630Z JUL 05
FROM CDRAMCOM, REDSTONE ARSENAL, AL //AMSAM-SF-A//
SUBJECT - AVIATION SAFETY ACTION MESSAGE (ASAM), MAINTENANCE
MANDATORY, RCS CSGLD-1860(R1), H-47 SERIES AIRCRAFT, AFT
TRANSMISSION RETAINER, CH-47-05-ASAM-04
.... This message is effective until rescinded or superseded.
.....NOTE.....
....This message is issued IAW AR 95-1 and has not been
....transmitted to units subordinate to addressees.
.... Addressees will immediately retransmit this message
....to all subordinate units, activities or elements
....affected or concerned. MACOMs will immediately
....verify this transmission to the AMCOM SOF Compliance
....Officer (AMSAM-SF-A, safeadm@redstone.army.mil).
.....NOTE.....
....MACOM commanders may authorize temporary exception from
....message requirements IAW AR 95-1, Ch 6. Exception may
....only occur when combat operations or matter of life or
....death in civil disasters or other emergencies are so
....urgent that they override the consequences of continued
....aircraft operation.
.....NOTE.....
....Commanders unable to comply with the requirements of
....this message within the time frame specified will change
....the affected aircraft status symbol to a Red //X//.
1. SUMMARY -
1.1. Background - An unknown number of H-47 aft transmissions
have been assembled omitting the Liner (PN 145D2304-4) or with
the ball bearing outer race retention key mechanically removed
from the liner. The Liner is a subcomponent of the Seal Retainer
Assembly (PN 145D2304-9). Installation of the Seal Retainer
assembly is identified in DMWR 55-1615-324 with a Warning to be
an Installation Critical, Critical Safety Item but is not
included in the TM.
1.2. Message Purpose -
1.2.1. Ensure proper assembly of the Aft Transmission to prevent
unnecessary wear from bearing race spinning, bearing spalling,
and premature transmission failure.
1.2.2. Emphasize to the fleet proper installation of the Seal
Retainer Assembly.
1.2.3. Require one-time visual inspection of the Seal Retainer
Assembly for proper installation of the Liner.
1.2.4. Revise the TMs to identify the assembly as installation
critical.
2. END ITEMS AFFECTED - All H-47 series aircraft.
3. ASSEMBLIES/COMPONENTS/PARTS AFFECTED -
3.1. Suspect/discrepant assemblies/components/parts -
..Nomenclature
                          PN
                                      NSN
..Seal Retainer Assembly
                          145D2304-9 5330-01-356-6164
3.2. Additional assemblies/components/parts to be inspected -
..Nomenclature
                           PN
```

```
..Transmission, Mechanical 145D2300-7 1615-01-315-4071
..Transmission, Mechanical 145D2300-6 1615-01-327-1297
..Transmission, Mechanical 145D2300-5 1615-01-296-3091
..Transmission, Mechanical 145D2300-4 1615-01-307-4842
.....NOTE.....
....When complying with the requirements of this message,
....complete forms and records entries IAW DA PAM 738-751.
.... ULLS-A units will use appropriate "E" forms.
4. INITIAL TAMMS (THE ARMY MAINTENANCE MANAGEMENT SYSTEM)
COMPLIANCE REQUIREMENTS -
4.1. Upon receipt of this message, make the following entry on
the DA Form 2408-13-1. Enter a Red Horizontal Dash //-// status
symbol with the following statement: "Comply with requirements of
CH-47-05-ASAM-04 during next phase but NLT 31 Jul 07."
.....NOTE.....
.... The TAMMS compliance reporting form is available at
.... "www.redstone.army.mil/sof/tamms.xls" (use lower case
....letters only) or may be obtained from the units
....servicing LAR. Alternate forms may be approved by
....the AMCOM SOF Compliance Officer.
.....NOTE.....
.... The TAMMS Compliance Report only confirms the unit has
....made the initial logbook entry for assigned aircraft.
....TAMMS Compliance Reports will include aircraft serial
....numbers (in numerical order), date of entry on DA Form
....2408-13-1, unit address, local POC name and phone number.
4.2. TAMMS Compliance Report - Submit TAMMS Compliance Report
via priority email to "safeadm@redstone.army.mil" NLT 4 AUG 05
IAW AR 95-1. If email is not available, the report may be faxed
to: SOF Compliance Officer at DSN 897-2111 or (256) 313-2111.
5. TASK/INSPECTION COMPLIANCE REPORTING REQUIREMENTS -
.....NOTE.....
.... The Task/Inspection Reporting Form is available at
.... "www.redstone.army.mil/sof/log.xls" (use lower case
....letters only) or may be obtained from the units
....servicing LAR. This report will cite the message
....number, date of inspection, aircraft serial number,
....aircraft hours, component serial number, component
....hours, and results of the inspection.
5.1. Aircraft - Submit Task/Inspection Compliance Report for
this message to Log POC NLT 3 Aug 07.
5.2. Retail Stock (Installation level and below) - N/A.
5.3. Wholesale Stock (Including Depot stock, Depot Maintenance
and Single Stock Fund) - N/A.
6. SPECIAL PROVISIONS TO MESSAGE REQUIREMENTS (AIRCRAFT) -
6.1. Aircraft in AVIM or Depot level maintenance - Commanders,
facility managers and contractors will not issue aircraft until
they are in compliance with this message.
6.2. Aircraft at Contractor Facility - Boeing will ensure DD 250
aircraft are in compliance with this message prior to departure.
7. TECHNICAL PROCEDURES/INSTRUCTIONS - Complete the following
during next phase but NLT 31 Jul 07.
```

```
.....Critical Safety Item.....
.... Seal Retainer Assembly (PN 145D2304-9) is installation
....Critical. Any aft transmission that is known to have been
....installed without a 145D2304-4 liner or that had the liner
....either removed or the locking tab machined should be subject
....to the repair procedure identified in para 7 of this ASAM
....as soon as possible to preclude having to replace the
....transmission due to damage from bearing rotation progressing
....until the phase inspection.
7.1. Inspect for the installation of the liner (PN 145D2304-4)
and the liner locking key feature as follows. For item
depictions, refer to TM 55-1520-240-23P (CH-47), fig 191,
items 143/144 or TM 1-1520-252-23P (MH-47), fig 06-9, item 154.
7.1.1. Lower Aft Transmission IAW TM 55-1520-240-23-5,
Task 6-92 (through step 31 only) or TM 1-1520-252-23-6,
Task 6-110 (through step 37 only).
7.1.2. Remove Seal Retainer IAW TM 55-1520-240-23-5 Task 6-90
steps 2 and 3 or TM 1-1520-252-23-6 Task 6-108 steps 2 and 3.
7.1.3. Inspect for the installation of the liner (PN 145D2304-4)
and the liner locking key feature.
7.1.3.1. If either the liner or locking key feature are not
installed, proceed to para 7.2.
7.1.3.2. If the liner and locking key feature are installed,
reinstall seal retainer on rotor shaft IAW TM 55-1520-240-23-5,
Task 6-91, steps 7 through "Follow on Maintenance" or
TM 1-1520-252-23-6, Task 6-109, steps 7 through "Follow on
Maintenance". Proceed to para 7.5.
7.2. Inspect transmission for damage resulting from bearing
rotation.
7.2.1. Using a depth gage or a dial caliper, measure from the
top machined surface of the top cover (PN 145D2301-3) to the top
surface of the bearing (PN 145DS200-2). (Do not measure to the
bottom of the key-slot). If this dimension exceeds 0.500 inch,
the aft transmission will be considered unserviceable and will
require return to overhaul.
7.2.2. Conduct inspection of the surface of the seal retainer
housing (PN 145D2304-8) (360 degrees inspection) where the liner
(PN 145D2304-4) should have been installed. The transmission is
considered unserviceable if the wear on the liner mounting
surface of the seal retainer is equal to or greater than 0.010
inch.
7.3. If the transmission is unserviceable, make the following
entry on the DA Form 2408-13-1. Enter a Red //X// status symbol
with the following statement: "Aft transmission unserviceable IAW
CH-47-05-ASAM-04, para ###." Insert appropriate para number for
the unserviceable condition.
7.4. If the transmission passes the inspections above, install
new seal retainer on rotor shaft IAW TM 55-1520-240-23-5,
Task 6-91, steps 7 through "Follow on Maintenance" or
TM 1-1520-252-23-6, Task 6-109, steps 7 through "Follow On
Maintenance".
7.5. Clear the initial entry from para 4.1. and note compliance
on DA Form 2408-5-1 (Aft Transmission).
8. PROCEDURES/INSTRUCTIONS FOR ASSEMBLIES/COMPONENTS/PARTS IN
WORK OR IN STOCK (AT ALL LEVELS INCLUDING WAR RESERVES) - N/A.
9. SPECIAL TOOLS AND FIXTURES REQUIRED - N/A.
10. SUPPLY/PARTS (REQUISITION/DISPOSITION) -
10.1. Parts Required -
                                   Qty
..Nomenclature
                      PN/NSN
                                            Cost ea.
```

\$482473.00 \$482473.00

..Transmission, Mech. 145D2300-7 1

```
12.2.2. TM 55-1520-240-23-5 Task 6-91, prior to step 10 insert:
.....WARNING.....
.....Critical Safety Item.....
.... Seal Retainer Assembly (15) is installation Critical.
....Only an unmodified 145D2304-9 Seal Retainer Assembly
....is to be installed.
12.2.3. TM 55-1520-240-23-5 Task 6-97, prior to step 5 insert:
.....WARNING.....
.....Critical Safety Item.....
.... Seal Retainer Assembly (4) is installation Critical.
....Only an unmodified 145D2304-9 Seal Retainer Assembly
....is to be installed.
12.2.4. TM 1-1520-252-23-6 Task 6-73, prior to step 4 insert:
.....WARNING.....
.....Critical Safety Item.....
.... Seal Retainer Assembly (1) is installation Critical.
....Only an unmodified 145D2304-9 Seal Retainer Assembly
....is to be installed.
12.2.5. TM 1-1520-252-23-6 Task 6-109, prior to step 11 insert:
.....WARNING.....
.....Critical Safety Item.....
.... Seal Retainer Assembly (1) is installation Critical.
....Only an unmodified 145D2304-9 Seal Retainer Assembly
....is to be installed.
12.2.6. TM 1-1520-252-23-6 Task 6-116, prior to step 5 insert:
.....WARNING.....
.....Critical Safety Item.....
.... Seal Retainer Assembly (4) is installation Critical.
....Only an unmodified 145D2304-9 Seal Retainer Assembly
....is to be installed.
13. POINTS OF CONTACT -
13.1. Technical POCs are -
13.1.1. Primary - Mr. Keith Clancy, AMSRD-AMR-AE-C, DSN 897-
3382 or (256) 313-3375. Fax is 897-4726 or (256) 313-4726.
Email is "keith.clancy@us.army.mil".
13.1.2. Alternate - Mr. Tim Rickmeyer, AMSRD-AMR-AE-C, DSN 645-
6485 or (256) 955-6485. Fax is 897-4726 or (256) 313-4726.
Email is "timothy.rickmeyer@us.army.mil".
13.2. Logistical POCs are -
13.2.1. Primary - Mr. Bill Olson, SFAE-AV-CH, DSN 897-0721 or
(256) 313-0721. Fax is 897-4726 or (256) 313-4726. Email is
"william.olson@peoavn.redstone.army.mil".
13.2.2. Alternate - Mr. Mark Samuelson, SFAE-AV-CH, DSN 897-0726
or (256) 313-0726. Fax is 897-4726 or (256) 313-4726. Email is
"mark.samuelson1@us.army.mil".
13.3. Wholesale Materiel POC (spares) is Mr. Robert King,
AMSAM-MMC-AV-CA, DSN 897-3363 or (256) 313-3363. Fax is
DSN 645-6453. Email is "robert.king@redstone.army.mil".
13.4. Forms and Records POCs are -
13.4.1. Primary - Ms. Ann Waldeck, AMSAM-MMC-MA-NM, DSN 746-5564
or (256) 876-5564. Fax is DSN 746-4904 or (256) 876-4904. Email
is "ann.waldeck@redstone.army.mil".
13.4.2. Alternate - Ms. Sibyl Johnson, AMSAM-MMC-MA-NM, DSN 788-
6696 or (256) 842-6696. Fax is DSN 746-4904 or (256) 876-4904.
Email is "sibyl.johnson@redstone.army.mil".
13.5. Safety POCs are -
13.5.1. Primary - Mr. Randall Rushing (SAIC), AMSAM-SF-A, DSN
897-2092 or (256) 313-2092. Fax is DSN 897-2111 or (256) 313-
2111. Email is randall.rushing@redstone.army.mil".
13.5.2. Alternate - Mr. Russell Peusch, AMSAM-SF-A, DSN 788-8632
```