

MISHAP REPORT

CH47C IIAAS - 4078 (D032)

IRAN


17 July 1977 0700 Hours (Local Time)

MAJOR ACCIDENT

Aircraft was on approach with sling load when No. 1 Engine chip lite illuminated. Sling load was dropped on pad and aircraft landed.

Immediately after the initial landing the aircraft took off and landed three times in rapid order. The aircraft sustained, during this period of time, damage to the forward and aft rotor blades, (1) one landing gear and tire, chin hubble and rudder pedals.

There was no report of injuries and the aircraft is considered repairable.



R. G. Orr

RGO:sam
P41-36,X7937