

MISHAP REPORT

August 6, 1976

147th AVIATION CO.
A/C 69-17108 CH47C
Barbers Point, Hawaii
5 August 1976
Preliminary Report

Aircraft had completed refueling and was taxiing when pilots reported a high frequency vibration. The aircraft then broke up and a fire erupted and destroyed the aircraft.

None of the crew were reported injured.

USAAVS has dispatched personnel to assist in the investigation. Boeing personnel are awaiting a request for technical assistance. Will depart when received.


R. G. ORR

RGorr:rsw
P41-36:7937